Oil Field Environmental Incident Summary

Responsible Party: Rampart Energy

Well Operator: ARSENAL ENERGY USA INC.

Well Name: BUNTING 1

Field Name: RENNIE LAKE Well File #: 5776

Date Incident:9/12/2016Time Incident:08:45Facility ID Number:County:BURKETwp:162Rng:91Sec:27Qtr:

Location Description: Light mist of oil on harvested field.

Submitted By: Gary Ramsdell Received By:

Contact Person: Gary Ramsdell

1512 Larimer Street

Suite 550

Denver, CO 80202

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building:1 MileDistance Nearest Water Well:1 Mile

Type of Incident: Treater Leak

Release Contained in Dike: No Reported to NRC: Unknown

Spilled Units Recovered Units Followup Units
Oil 6 Barrels 5 Barrels 5.75 barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 10/21/2016 Clean Up Concluded: 10/7/2016

Risk Evaluation:

Light mist of oil made for explosive atmosphere, Treater flame was not burning so risk was reduced.

Areal Extent:

Some oil from leak fell inside dyke, Mist covered approximately 95 feet by 35 feet.

Potential Environmental Impacts:

Impact to ground water is very low. Impact to soil is low to moderate.

Action Taken or Planned:

Spill was contained by shutting in well and draining down treater to relieve pressure, Treater was emptied by vac truck and fluid from treater put into tanks on location. 5 of the 6 bbls of oil released was recovered with vac truck and roustabouts. Met with landowner concerning light mist in farmed field.

Wastes Disposal Location: Recovered fluid was taken to Dakota Blue Disposal South West of Lignite.

Agencies Involved:

,,,	-	_	_	4-	_
	n	п	-	то	
v	\sim	u	u	te	v

Date: 9/13/2016 Status: Reviewed - Follow-up Required Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a treater leak, was not contained according to the report. Further follow-up needed.

Date: 9/14/2016 Status: Inspection Author: Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site at 12:40 p.m. 65 degrees F, sunny, wind 7 mph SSE. SE side of treater is coated in oil. Mist from treater leak extends to south of treater. Light oiling into grass in field to the south remains.